

**ENVIRONMENTAL SITE ASSESSMENT
FOR THE
EVALUATION OF POTENTIALLY
HAZARDOUS MATERIALS**

*Vacant area
9301 Merle St.
Houston, Texas 77033*

Prepared for

City of Houston
Building Services Department
P.O. Box 1562
Houston, Texas 77251

Attn.: Mr. Gabriel Mussio

Date of the report: 01/09/06

Prepared by

RAO ENVIRONMENTAL
19333 Hwy. 59 North, Suite 190
Humble, Texas 77338

Tel: 281-548-7050

Fax: 281-548-7030

TABLE OF CONTENTS

1.0	EXECUTIVE SUMMARY	1
2.0	OBJECTIVE	3
2.1	Scope of work	3
2.2	Client authorization	3
2.3	Limitations and assessment	3
3.0	SITE LOCATION AND DESCRIPTION	4
4.0	ENVIRONMENTAL SETTING	5
4.1	Surface water characteristics	5
4.2	Groundwater characteristics	5
5.0	ENVIRONMENTAL REGULATORY REVIEW	6
5.1	Federal and State Regulatory Agency Inquiries	6
5.2	Local Government Inquiries	8
6.0	HISTORICAL USAGE INFORMATION	9
6.1	Current ownership	9
6.2	Prior ownership	9
6.3	Historical City Directories and Fire Insurance Maps	9
6.4	Review of the aerial photos	10
7.0	RESULTS OF THE ON-SITE INSPECTION	11
7.1	Observations	11
7.2	Hazardous substance identification/inventory	12
7.3	PCBs and Radon	12
7.4	Lead paint containing materials	12
7.5	Sampling results	12
8.0	FINDINGS AND CONCLUSIONS	13
9.0	REFERENCES	14
10.0	APPENDICES	
	Appendix-A Record of communications	
	Appendix-B Recorded chain of title	
	Appendix-C Facilities found in the area of review	
	Appendix-D Aerial photographs	
	Appendix-E Site photographs	

1.0 EXECUTIVE SUMMARY

This report represents results of an Environmental Site Assessment of a vacant property located at 9301 Merle St., Houston, Texas 77033. The subject site was inspected on December 22, 2005 by Mr. Zahir Jamal of RAO ENVIRONMENTAL. The subject property is a vacant land and is 53,260 square feet in area. The site was a former water well site. The site has vacant, grass covered areas with weeds and trees. Hazardous materials were not found at the site. Review of the title search does not indicate previous property ownership which might indicate possible environmental concerns about the site.

Review of the regulatory lists indicates that the subject property is not listed as a NPL (National Priority List), ERNS (Emergency Response Notification System), CERCLIS (Comprehensive Environmental Response, Compensation and Liability Information System), RCRIS (Resource Conservation And Recovery Information System), LPST (Leaking Underground Petroleum Storage Tanks), UST (Underground Petroleum Storage Tanks), TSD (Treatment, Storage, and Disposal) or a LANDFILL facility. Adjacent sites and sites within the half-mile radius are not listed as NPL (National Priority List), CERCLIS (Comprehensive Environmental Response, Compensation and Liability Information System), TSD (Treatment, Storage, and Disposal) and LANDFILL facilities.

Four facilities within the half-mile radius appear on the LPST (Leaking Underground Petroleum Storage Tanks) facilities list. Final concurrences were issued and the cases were closed for the facilities on 8510 and 9030 Martin Luther King Blvd. Final concurrence is pending for the facility on 8520 Martin Luther King Blvd. The facility on 8601 Martin Luther King Blvd. is under site assessment. These two facilities are not adjacent to the property and, therefore, would not pose a contamination threat to the subject site. One facility within the half-mile radius appears on the RCRIS (Resource Conservation And Recovery Information System) facilities list. No violations or enforcements are present at the listed facility. One facility within the half-mile radius appears on the ERNS (Emergency Response Notification System) list. The listed facility has been properly attended to. In addition, this facility is not adjacent to the property and, therefore, emergency response at this site is not of environmental concern to the subject site. Three facilities within the half-mile radius appear on the UST (Underground Petroleum Storage Tanks) facilities list.

The Phase 1 ESA based on the on-site inspection, review of the regulatory lists, inquiries with the local governmental agencies, review of the title search, and review of the aerial photos reveals that the site has a low risk with respect to the environmental concerns.

2.0 OBJECTIVE

2.1 Scope of work

The scope of the study included a site visit, a review of the site history, regulatory agency documentation and an environmental assessment of the property.

2.2 Client authorization

The study was authorized by Mr. Gabriel Mussio, Building Services Department, City of Houston, Houston, Texas and was performed for the client in evaluating potential environmental problems associated with the site. If any additional information is known or encountered regarding the site, it should be forwarded to this office for a possible reevaluation of conclusions.

2.3 Limitations and assessment

The Phase I Environmental Site Assessment consists of various studies including a review of the chain of title of the property, an on-site inspection of the site and its facilities, a review of the files at Government and Environmental Regulatory Agencies. All investigations in this study have been conducted in accordance with American Society for Testing and Materials and Standard Practice for Phase I Environmental Site Assessments.




Figure is an approximation

Figure1: Site map- 9301 Merle St., Houston, Texas 77033

Scale: 1" = 50 ft (approx.)

3.0 SITE LOCATION AND DESCRIPTION

The subject property is a vacant area and is 53, 260 square feet in area. The site was a former water well site. The site has vacant, grassy areas with weeds and trees. The site is legally described as follows:

“Lots 1,2, 3 and 4, Block 31, Sunnyside gardens, a subdivision located in the Henry A. Robinson Survey, Abstract No. 679, Harris County, Texas, according to the map recorded in Volume 26, Page 70, Harris County Map Records”.

The site is geographically located at Latitude $29^{\circ} 39' 25''$ and Longitude $95^{\circ} 20' 22''$. A site map is presented as Figure-1.



Topo Map

4.0 ENVIRONMENTAL SETTING

USGS Quadrangle Maps, Texas Water Development Board hydrogeological literature, conversations with the local officials and the Geologic Atlas of Texas were used to determine the environmental setting of the site and the general area.

4.1 Surface water characteristics

The elevation of the site is approximately 44 feet Above Mean Sea Level (AMSL) and can be seen on the Park Place Quadrangle Map. Nearest surface water feature is Sims Bayou. Surface water drainage is to the southeast.

4.2 Groundwater characteristics

Groundwater in the area is obtained from the Chicot and Evangeline aquifers. These units are composed of clay, sand and gravel which were deposited in the fluvial, deltaic, and shallow marine environments and are hydrologically connected. The Chicot aquifer consists of the Willis Sand, Bentley Formation and the Montgomery Formation, Beaumont Formation and overlies the Evangeline aquifer. The Evangeline aquifer consists of the upper most part of the Fleming Formation and the Goliad Sand.

Recharge to the aquifers is from precipitation that falls on the outcrop areas. These formations outcrop in belts that are nearly parallel to the Gulf of Mexico. The Goliad Sand is overlapped by younger formations east of the Brazos river and is not exposed at the surface in the coastal area.

The site is located on the Beaumont Formation which is of quaternary age and consists of mostly stream channel, point bar, natural levee, backswamp and to a lesser extent coastal marsh and mud flat deposits.




Environmental FirstSearch

1 Mile Radius

Single Map:



9301 MERLE ST, HOUSTON TX 77033



Source: 2002 U.S. Census TIGER Files

Target Site (Latitude: 29.656944 Longitude: -95.339488)


Identified Site, Multiple Sites, Receptor

NPL, Brownfield, Solid Waste Landfill (SWL) or Hazardous Waste

Railroads

Black Rings Represent 1/4 Mile Radius; Red Ring Represents 500 ft. Radius






Environmental FirstSearch

.5 Mile Radius

ASTM: CERCLIS, RCRATSD, LUST, SWL



9301 MERLE ST, HOUSTON TX 77033



Source: 2002 U.S. Census TIGER Files

Target Site (Latitude: 29.656944 Longitude: -95.339488)

Identified Site, Multiple Sites, Receptor

NPL, Brownfield, Solid Waste Landfill (SWL) or Hazardous Waste

Railroads

Black Rings Represent 1/4 Mile Radius; Red Ring Represents 500 ft. Radius












Environmental FirstSearch
.25 Mile Radius
ASTM: NFRAP, RCRAGEN, ERNS, UST, OTHER



9301 MERLE ST, HOUSTON TX 77033



Source: 2002 U.S. Census TIGER Files

- Target Site (Latitude: 29.656944 Longitude: -95.339488) 
- Identified Site, Multiple Sites, Receptor   
- NPL, Brownfield, Solid Waste Landfill (SWL) or Hazardous Waste 
- Railroads 
- Black Rings Represent 1/4 Mile Radius; Red Ring Represents 500 ft. Radius

5.0 ENVIRONMENTAL REGULATORY REVIEW

Established lists were checked to evaluate if the site or adjacent properties are reported as having possible environmental concerns. The following paragraphs discuss the agencies and lists conducted.

5.1 Federal and State Regulatory Agency Inquiries

NPL list

This is a list of sites established by Federal Government as having a priority for clean up. Many are superfund sites. The site does not appear on the NPL list. Adjacent sites and sites within the half-mile radius do not appear on the list.

CERCLIS list

The CERCLIS list is compiled by the Federal Government and includes sites which could possibly be contaminated and may require clean up. Many of the sites which appear on the CERCLIS list have been thoroughly investigated. The site, adjacent sites and sites within the half-mile radius do not appear on the list.

RCRIS FACILITIES list

The Resource Conservation and Recovery Information System (RCRIS) is a nationwide data base created to maintain and regulate facilities that handle hazardous waste. The RCRIS data base replaced the HWDMS (Hazardous Waste Data Management System) in September 1992 as a major system supporting the implementation of RCRA (Resource Conservation and Recovery Act). The site and adjacent sites do not appear on the list. One facility within the half-mile radius appears on the RCRIS facilities list. No violations or enforcements are present at the listed facility.

TSD list

The TSD list consists of facilities that have been registered to treat, store or dispose of hazardous wastes. These facilities are assigned a corresponding TSD number. The site, adjacent properties and properties within the half-mile radius do not appear on the list.

UST list

Owners of Underground Storage Tanks (USTs) are required to register their USTs along with the construction information regarding the UST system with the Texas Commission on Environmental Quality (TCEQ). The property and adjacent properties do not appear on the list. Three facilities within the half-mile radius appear on the UST facilities list.

LPST list

The LPST list consists of Petroleum Storage Tank Systems which have reported releases of greater than 25 gallons. The list is maintained by the Texas Commission on Environmental Quality under delegation from the EPA. The property and adjacent properties do not appear on the list. Four facilities within the half-mile radius appear on the LPST facilities list. Final concurrences were issued and the cases were closed for the facilities on 8510 and 9030 Martin Luther King Blvd. Final concurrence is pending for the facility on 8520 Martin Luther King Blvd. The facility on 8601 Martin Luther King Blvd. is under site assessment. These two facilities are not adjacent to the property and, therefore, would not pose a contamination threat to the subject site.

LANDFILL list

The landfill list is compiled and maintained by the Texas Department of Health and consists of sites identified as landfill, waste processing facility or sludge disposal facility. The site, adjacent properties and properties within the half-mile radius do not appear on the list.

ERNS list

EPA's emergency response notification system consists of a list of reported CERCLA hazardous substance releases or spills in quantities greater than the reportable quantity as maintained at the National Response Center. The site and adjacent sites do not appear on the list. One facility within the half-mile radius appears on the ERNS list. The listed facility has been properly attended to. This facility is not adjacent to the property and, therefore, is not of environmental concern to the subject site.

5.2 Other Local and State Government inquiries:

Harris County Pollution Control Department:

Ms. Fleda Key of the Harris County Pollution Control Department investigated the subject site for records of hazardous chemical spills. She indicated (ROC-1) that there were no chemical spills or accidental fires on record at the subject site during the last five (5) years.

6.0 HISTORICAL USAGE INFORMATION

Site history was investigated by reviewing the property information and aerial photos.

6.1 Current ownership

Review of the title search indicates that the property is currently owned by Harris County, Water Control and Improvement District No. 26.

6.2 Prior ownership

A copy of the title search is presented in Appendix-B. Review of the title search indicates that the property was never owned by those whose names would indicate possible environmental concerns about the site, such as Landfill companies and Hazardous Waste Storage and Treatment and Disposal facilities. The property was owned by Sam T. Robb et al in 1948. Since then, several companies and individuals owned the site. Harris County, Water Control and Improvement District No. 26. acquired the site in the year 1951.

6.3 Historical City Directories/ Fire Insurance Maps

Historical City Directories and Fire Insurance Maps were not available for this area.

6.4 Review of the aerial photographs

1944 aerial photo (1"= 700 ') shows the site as a vacant land. Vacant and residential sites are present to the far north, south, east and the west.

1953 aerial photo (1"= 700 ') shows the site as a vacant land with water well. Vacant and residential sites are present to the far north, south, east and the west.

1969 aerial photo (1"= 700 ') shows the site as a vacant land with water well. Vacant, residential and commercial sites are present to the far north, south, east and the west.

1979 aerial photo (1"= 700 ') shows the site as a vacant land with water well. Vacant, residential and commercial sites are present to the far north, south, east and the west.

1986 aerial photo (1"= 700 ') shows the site as a vacant land. Vacant, residential and commercial sites are present to the far north, south, east and the west.

1996 aerial photo (1"= 700 ') shows the site as a vacant land. Vacant, residential and commercial sites are present to the far north, south, east and the west.

2004 aerial photo (1"= 700 ') shows the site as a vacant land. Vacant, residential and commercial sites are present to the far north, south, east and the west.

7.0 RESULTS OF THE ON-SITE INSPECTION

The site was inspected on December 22, 2005 by Mr. Zahir Jamal of RAO ENVIRONMENTAL.

7.1 Observations

The subject property is a vacant land and is 53,260 square feet in area. The site was a former well site. The site has vacant, grassy areas with weeds and trees. Entrance to the site is from Merle St. Weeds, shrubs and trees are present to the eastern and northern boundary of the site. A small raised area covered in grass is present to the north of the site. The remainder of the site is grass covered. A gate is present to the southwest side of the site. The property is fenced. Drainage easement areas are present to the north and east of the site. No other developments or improvements were found at the site.

Vent lines, tankhold areas and steel caps indicative of the buried USTs were not found at the site.

Following is the list of property's usage at the adjacent properties.

- | | |
|------------------------------|--|
| Property usage-north: | Adjacent properties to the north are drainage easement and a residential area. |
| Property usage-south: | Adjacent property to the south is a residential area. |
| Property usage-east: | Adjacent properties to the east are drainage easement and a residential area. |
| Property usage-west: | Adjacent properties to the west are Merle St., and a Residential area. |

7.2 Hazardous substance identification/ inventory

Pesticides, solvents and other hazardous materials were not found at the site.

7.3 PCBs and Radon

PCB containing materials such as capacitors, transformers and light ballasts were not found at the sites. The sites are not in a EPA designated radon gas containing area. The soil at the subject sites, therefore, does not emit radon gas.

7.4 Lead Paint containing materials

Site is a vacant land.

7.5 Sampling results

Site is a vacant land.


8.0 FINDINGS AND CONCLUSIONS

The Phase 1 ESA based on the on-site inspection, review of the regulatory lists, inquiries with the local governmental agencies, review of the title search, and review of the aerial photos reveals that the site has a low risk with respect to the environmental concerns.

9.0 REFERENCES

1. Park Place Quadrangle, USGS Quadrangle Map.
2. Survey documents.
3. Texas Water Development Board, Report 310.
4. Geologic Atlas of Texas, Houston sheet.

Sincerely,

A handwritten signature in blue ink, appearing to read 'Rao Somepalli', with a stylized flourish at the end.

Rao Somepalli, Ph.D.

Project Manager

APPENDIX -A

RECORD OF COMMUNICATION

ROC-1

FROM: Ms. Fleda Key
Harris County Pollution Control Department

Tel #: 713-920-2831

TO: Rao Somepalli

DATE & TIME: December 27, 2005, 2:44 PM

SUMMARY OF COMMUNICATION:

There were no chemical spills on record at the subject site during the last five (5) years.

APPENDIX-B

**TEXAS ABSTRACT SERVICES
412 MAIN ST., SUITE 250
HOUSTON, TEXAS 77002**

HISTORICAL OWNERSHIP REPORT

January 4, 2006

Control No. 11642

Mr. Rao Somepali
Rao Environmental Consultants

Re: 9301 Merle Street

SUBJECT PROPERTY: Lots 1, 2, 3, and 4, Block 31, Sunnyside Gardens, a subdivision located in the Henry A. Robinson Survey, Abstract No. 679, Harris County, Texas, according to the map recorded in Volume 26, Page 70, Harris County Map Records.

Dear Mr. Somepali:

At your request, we have searched the records of the County Clerk of Harris County, Texas, pertaining to the property referenced above from January 1, 1955 to the present and have determined that the following list represents all of the deeds, surface leases and environmental liens of record within the said period.

DATE:	3-10-48
INSTRUMENT:	Map of Sunnyside Gardens
GRANTOR:	Sam T. Robb et al
GRANTEE:	The Public
COMMENTS:	315.65 acres
REFERENCE:	26/70 Map Records
DATE:	3-1-48
INSTRUMENT:	Warranty Deed
GRANTOR:	Sam T. Robb et al
GRANTEE:	Seaport Realty Company
COMMENTS:	Lots 1 through 10, Block 31 (and other property)
REFERENCE:	1795/121 Deed Records

Continued

Page 2


DATE: 9-20-51
INSTRUMENT: Warranty Deed
GRANTOR: Seaport Realty Company
GRANTEE: Bayou Sewer and Water Works, Inc.
COMMENTS: Lots 1, 2, 3, and 4
REFERENCE: 2374/276 Deed Records

DATE: 9-20-51
INSTRUMENT: Warranty Deed
GRANTOR: Bayou Sewer and Water Works, Inc.
GRANTEE: Harris County Water Control and Improvement District No. 26
COMMENTS: Lots 1, 2, 3, and 4
REFERENCE: 3559/117 Deed Records

Current through December 28, 2005

Texas Abstract Services disclaims any warranties, expressed or implied concerning this information. Texas Abstract Services' liability for errors or omissions in this information shall be limited to the amount paid for this report. By accepting this form, the party requesting the information agrees that the disclaimer of warranties and liability limitation contained in this paragraph is a part of its contract with Texas Abstract Services and shall cover all actions whether arising hereunder by statute, in contract or in tort.


TEXAS ABSTRACT SERVICES


Jessica M. Lightfoot

Harris County Appraisal District



0 100 200
PUBLICATION DATE:
10/13/2005



MAP LOCATION



**FACET
5453D**

1	2	3	4
5	6	7	8
9	10	11	12



5453D6

5453D11



Banks Information Solutions, Inc.

Environmental FirstSearch™ Report

TARGET PROPERTY:

9301 MERLE ST

HOUSTON TX 77033

Job Number: 31199

PREPARED FOR:

Rao Environmental

19333 Hwy 59 North, Ste. 190

Humble, TX 77338

01-04-06

Environmental
FIRSTSEARCH



Tel: (512) 478-0059

Fax: (512) 478-1433

APPENDIX-C



Banks Information Solutions, Inc.

Environmental FirstSearch™ Report

TARGET PROPERTY:

9301 MERLE ST

HOUSTON TX 77033

Job Number: 31199

PREPARED FOR:

Rao Environmental

19333 Hwy 59 North, Ste. 190

Humble, TX 77338

01-04-06



Tel: (512) 478-0059

Fax: (512) 478-1433

**Environmental FirstSearch
Site Information Report**

Request Date: 01-04-06
Requestor Name: Rao
Standard: ASTM

Search Type: COORD
Job Number: 31199
Filtered Report

TARGET ADDRESS: 9301 MERLE ST
HOUSTON TX 77033

Demographics

Sites: 9	Non-Geocoded: 0	Population: NA
Radon: NA		

Site Location

	<u>Degrees (Decimal)</u>	<u>Degrees (Min/Sec)</u>		<u>UTMs</u>
Longitude:	-95.339488	-95:20:22	Easting:	273552.893
Latitude:	29.656944	29:39:25	Northing:	3282882.662
			Zone:	15

Comment

Comment:

Additional Requests/Services

Adjacent ZIP Codes: 1 Mile(s)

Services:

ZIP Code	City Name	ST	Dist/Dir	Sel
77048	HOUSTON	TX	0.71 SW	Y
77051	HOUSTON	TX	0.96 SW	Y

	Requested?	Date
Sanborns	No	
Aerial Photographs	No	
Historical Topos	No	
City Directories	No	
Title Search	No	
Municipal Reports	No	
Online Topos	No	

Environmental FirstSearch Search Summary Report

Target Site: 9301 MERLE ST
HOUSTON TX 77033

FirstSearch Summary

Database	Sel	Updated	Radius	Site	1/8	1/4	1/2	1/2>	ZIP	TOTALS
NPL	Y	10-07-05	1.00	0	0	0	0	0	0	0
CERCLIS	Y	10-07-05	0.50	0	0	0	0	-	0	0
NFRAP	Y	08-01-05	0.25	0	0	0	-	-	0	0
RCRA TSD	Y	09-22-05	0.50	0	0	0	0	-	0	0
RCRA COR	Y	09-22-05	1.00	0	0	0	0	0	0	0
RCRA GEN	Y	06-13-05	0.25	0	0	1	-	-	0	1
ERNS	Y	12-31-04	0.25	0	0	1	-	-	0	1
State Sites	Y	01/05/05	1.00	0	0	0	0	0	0	0
SWL	Y	09-16-02	0.50	0	0	0	0	-	0	0
Other	Y	06/27/05	0.25	0	0	0	-	-	0	0
REG UST/AST	Y	07/13/05	0.25	0	0	3	-	-	0	3
Leaking UST	Y	06/27/05	0.50	0	0	1	3	-	0	4
- TOTALS -				0	0	6	3	0	0	9

Notice of Disclaimer

Due to the limitations, constraints, inaccuracies and incompleteness of government information and computer mapping data currently available to Banks Information Solutions, Inc., certain conventions have been utilized in preparing the locations of all federal, state and local agency sites residing in Banks Information Solutions, Inc.'s databases. All EPA NPL and state landfill sites are depicted by a rectangle approximating their location and size. The boundaries of the rectangles represent the eastern and western most longitudes; the northern and southern most latitudes. As such, the mapped areas may exceed the actual areas and do not represent the actual boundaries of these properties. All other sites are depicted by a point representing their approximate address location and make no attempt to represent the actual areas of the associated property. Actual boundaries and locations of individual properties can be found in the files residing at the agency responsible for such information.

Waiver of Liability

Although Banks Information Solutions, Inc. uses its best efforts to research the actual location of each site, Banks Information Solutions, Inc. does not and can not warrant the accuracy of these sites with regard to exact location and size. All authorized users of Banks Information Solutions, Inc.'s services proceeding are signifying an understanding of Banks Information Solutions, Inc.'s searching and mapping conventions, and agree to waive any and all liability claims associated with search and map results showing incomplete and or inaccurate site locations.

***Environmental FirstSearch
Sites Summary Report***

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

TOTAL: 9 **GEOCODED:** 9 **NON GEOCODED:** 0 **SELECTED:** 0

Map ID	DB Type	Site Name/ID/Status	Address	Dist/Dir	Page No.
2	ERNS	TEXAS PETROCHEMICAL 562511/PLANT	8800 PARK PL HOUSTON TX 77017	0.24 SE	1
6	LUST	FORMER GAS STA 112327	8601 MARTIN LUTHER KING BL HOUSTON TX 77033	0.22 NE	2
5	LUST	EXXON CO USA 64810 113114	8520 MARTIN LUTHER KING HOUSTON TX 77033	0.26 NE	7
5	LUST	EXXON CO USA 6 4810 107252	8510 MARTIN LUTHER KING HOUSTON TX	0.26 NE	11
7	LUST	SOUTHPARK MARKET 112793	9030 MARTIN LUTHER KING BL HOUSTON TX 77007	0.34 SE	12
1	RCRAGN	EXXON CO USA #64810 TXD988030391/VGN	8520 M KING BLVD HOUSTON TX 77033	0.25 NE	16
4	UST	DIAMOND SHAMROCK 703 0040171	8626 MARTIN LUTHER KING JR HOUSTON TX 77033	0.19 NE	17
3	UST	ANA FOOD STORE 0057228	8607 MARTIN LUTHER KING BL HOUSTON TX 77033	0.20 NE	20
6	UST	MLK SHELL 0007866	8601 MLK BLVD HOUSTON TX 77033	0.22 NE	23

Environmental FirstSearch
Site Detail Report

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 8

DIST/DIR: 0.22 NE

MAP ID: 6

NAME: FORMER GAS STA
ADDRESS: 8601 MARTIN LUTHER KING BLVD
HOUSTON TX 77033
HARRIS
CONTACT: ASSAD BOULOS

REV: 06/27/05
ID1: 112327
ID2: 0007866
STATUS:
PHONE: 713/854-8532

SITE INFORMATION

REPORTED:
ENTERED INTO SYSTEM: 5/27/1997
SITE PRIORITY: gw impacted, no apparent threats or impacts to receptors
SITE STATUS: Site assessment
PRP: A & A INC
PRP ADDRESS: PO BOX 91098
HOUSTON TX 77291
PRP CONTACT: ASSAD BOULOS
PRP PHONE: 713/854-8532

LUST INFORMATION

TANK NUMBER: 1
STATUS: Removed From Ground
STATUS DATE: 05051997
INSTALL DATE: 01011983
REGISTERED DATE: 05081986
CAPACITY: 0010000 Gallons
EXT CONTAINMENT DESIGN: Single Wall -
-
CONSTRUCTION MATERIAL: Fiberglass Reinforced Plastic (FRP)
CORROSION PROTECTION: Ext Dielectric Coating/Laminate/Tape/Wrap - FRP Tank or Piping (Noncorrodible)
-
CORROSION PROT VARIANCE: No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported
STG 1 EQUIP INSTALL DATE:
STG 2 VAPOR RECOVERY EQUIP STATUS:
STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:
INSTALLER NAME:
INSTALLER LICENSE NUMBER:

TYPE OF PIPE:
PIPE MATERIAL: Fiberglass Reinforced Plastic (FRP)
PIPE DESIGN EXT CONTAINMENT: Single Wall -
- -
PIPE CONECTORS & VALVES: - -
PIPE CORROSION PROTECTION: Ext Dielectric Coating/Laminate/Tape/Wrap - FRP Tank or Piping (Noncorrodible)
-
PIPE CORROSION PROT VARIANCE: No Variance

SUBSTANCE STORED: GASOLINE
TANK RLSE DETECTION METHODS: - - - None
TANK RLSE DETECTION VARIANCE: No Variance
PIPE RLSE DETECTION METHODS: - - - None
PIPE RLSE VARIANCE: No Variance
SPILL/OVERFILL PREVENTION: - -
SPILL/OVERFILL VARIANCE: No Variance

- Continued on next page -

JOB: 31199

MAP ID: 6

REV: 06/27/05
ID1: 112327
ID2: 0007866
STATUS:
PHONE: 713/854-8532

CONSTRUCTION MATERIAL:	Fiberglass Reinforced Plastic (FRP)
CORROSION PROTECTION:	FRP Tank or Piping (Noncorrodible) - Ext Dielectric Coating/Laminates/Tape/Wrap

Environmental FirstSearch

Site Detail Report

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 8 **DIST/DIR:** 0.22 NE **MAP ID:** 6

NAME: FORMER GAS STA
ADDRESS: 8601 MARTIN LUTHER KING BLVD
HOUSTON TX 77033
HARRIS
CONTACT: ASSAD BOULOS

REV: 06/27/05
ID1: 112327
ID2: 0007866
STATUS:
PHONE: 713/854-8532

PIPE CONECTORS & VALVES: - -
PIPE CORROSION PROTECTION: -
-
PIPE CORROSION PROT VARIANCE: No Variance
SUBSTANCE STORED: GASOLINE
TANK RLSE DETECTION METHODS: SIR (Stat. Inventory Reconciliation) & Inventory Cntrl - -
TANK RLSE DETECTION VARIANCE: No Variance
PIPE RLSE DETECTION METHODS: SIR (Stat. Inventory Reconciliation) & Inventory Cntrl - -
PIPE RLSE VARIANCE: No Variance
SPILL/OVERFILL PREVENTION: Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Off Valve (ADSV) - Factory Built
Spill Container/Bucket/Sump
SPILL/OVERFILL VARIANCE: No Variance

TANK NUMBER: 2
STATUS: In Use
STATUS DATE:
INSTALL DATE: 05151997
REGISTERED DATE: 01222001
CAPACITY: 0008000 Gallons
EXT CONTAINMENT DESIGN: Single Wall -
-
CONSTRUCTION MATERIAL: Fiberglass Reinforced Plastic (FRP)
CORROSION PROTECTION: Cathodic Protection-Factory Intalled -
-
CORROSION PROT VARIANCE: No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS: Two-Point System or Coaxial System
STG 1 EQUIP INSTALL DATE: 01011996
STG 2 VAPOR RECOVERY EQUIP STATUS: Balance System or Assist System
STG 2 EQUIP INSTALL DATE: 01011999

INSTALLER COMPANY:
INSTALLER NAME:
INSTALLER LICENSE NUMBER:

TYPE OF PIPE: Pressurizes
PIPE MATERIAL: Fiberglass Reinforced Plastic (FRP)
PIPE DESIGN EXT CONTAINMENT: Single Wall -
PIPE CONECTORS & VALVES: - -
PIPE CORROSION PROTECTION: -
-
PIPE CORROSION PROT VARIANCE: No Variance

SUBSTANCE STORED: GASOLINE
TANK RLSE DETECTION METHODS: SIR (Stat. Inventory Reconciliation) & Inventory Cntrl - -
TANK RLSE DETECTION VARIANCE: No Variance
PIPE RLSE DETECTION METHODS: SIR (Stat. Inventory Reconciliation) & Inventory Cntrl - -
PIPE RLSE VARIANCE: No Variance
SPILL/OVERFILL PREVENTION: Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Off Valve (ADSV) - Tight - Fill
Fitting

Continued on next page

Environmental FirstSearch
Site Detail Report

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 8

DIST/DIR: 0.22 NE

MAP ID: 6

NAME: FORMER GAS STA
ADDRESS: 8601 MARTIN LUTHER KING BLVD
HOUSTON TX 77033
HARRIS
CONTACT: ASSAD BOULOS

REV: 06/27/05
ID1: 112327
ID2: 0007866
STATUS:
PHONE: 713/854-8532

SPILL/OVERFILL VARIANCE: No Variance

TANK NUMBER: 3
STATUS: In Use
STATUS DATE:
INSTALL DATE: 05151997
REGISTERED DATE: 01222001
CAPACITY: 0008000 Gallons
EXT CONTAINMENT DESIGN: Single Wall -
-

CONSTRUCTION MATERIAL: Fiberglass Reinforced Plastic (FRP)
CORROSION PROTECTION: Cathodic Protection-Factory Installed -
-

CORROSION PROT VARIANCE: No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported
STG 1 EQUIP INSTALL DATE:
STG 2 VAPOR RECOVERY EQUIP STATUS:
STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:
INSTALLER NAME:
INSTALLER LICENSE NUMBER:

TYPE OF PIPE: Pressurizes
PIPE MATERIAL: Fiberglass Reinforced Plastic (FRP)
PIPE DESIGN EXT CONTAINMENT: Single Wall -
PIPE CONECTORS & VALVES: - -
PIPE CORROSION PROTECTION: -
-

PIPE CORROSION PROT VARIANCE: No Variance

SUBSTANCE STORED: DIESEL
TANK RLSE DETECTION METHODS: SIR (Stat. Inventory Reconciliation) & Inventory Cntrl - - -
TANK RLSE DETECTION VARIANCE: No Variance
PIPE RLSE DETECTION METHODS: SIR (Stat. Inventory Reconciliation) & Inventory Cntrl - - -
PIPE RLSE VARIANCE: No Variance
SPILL/OVERFILL PREVENTION: Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Off Valve (ADSV) - Tight - Fill
Fitting
SPILL/OVERFILL VARIANCE: No Variance

JOB: 31199

SEARCH ID: 7 DIST/DIR: 0.26 NE MAP ID: 5

NAME: EXXON CO USA 64810
ADDRESS: 8520 MARTIN LUTHER KING
HOUSTON TX 77033
HARRIS
CONTACT: JEFF JANOCIK

REV: 06/27/05
ID1: 113114
ID2: 0026673
STATUS:
PHONE: 214/-

REPORTED:	2/19/1998
ENTERED INTO SYSTEM:	4/16/1998
SITE PRIORITY:	gw impacted, no apparent threats or impacts to receptors
SITE STATUS:	Final concurrence pending documentation of well plugging
PRP:	EXXON MOBIL CORP
PRP ADDRESS:	PO BOX 650232 DALLAS TX 75247
PRP CONTACT:	JEFF JANOCIK
PRP PHONE:	214/-

TANK NUMBER:	3
STATUS:	Removed From Ground
STATUS DATE:	08261997
INSTALL DATE:	01011985
REGISTERED DATE:	05081986
CAPACITY:	0012000 Gallons
EXT CONTAINMENT DESIGN:	Single Wall -
	-
CONSTRUCTION MATERIAL:	Fiberglass Reinforced Plastic (FRP)
CORROSION PROTECTION:	FRP Tank or Piping (Noncorrodible) -
	-
CORROSION PROT VARIANCE:	No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported
STG 1 EQUIP INSTALL DATE:	
STG 2 VAPOR RECOVERY EQUIP STATUS:	
STG 2 EQUIP INSTALL DATE:	

INSTALLER COMPANY:
INSTALLER NAME:
INSTALLER LICENSE NUMBER:

TYPE OF PIPE:	
PIPE MATERIAL:	Fiberglass Reinforced Plastic (FRP)
PIPE DESIGN EXT CONTAINMENT:	Single Wall - -
PIPE CONECTORS & VALVES:	- -
PIPE CORROSION PROTECTION:	FRP Tank or Piping (Noncorrodible) -
	- Non Corrodible Material
PIPE CORROSION PROT VARIANCE:	No Variance

SUBSTANCE STORED:	GASOLINE
TANK RLSE DETECTION METHODS:	- - - Inventory Control
TANK RLSE DETECTION VARIANCE:	No Variance
PIPE RLSE DETECTION METHODS:	Auto Leak Line Detector (3.0gph for pressure piping) - - - Tightness Testing
PIPE RLSE VARIANCE:	No Variance
SPILL/OVERFILL PREVENTION:	Auto Flow Restrictor Valve (AFRV) - Factory Built Spill Containment Buckets/Spill Tight -
Fill Fitting	

Continued on next page

Continued on next page

Environmental FirstSearch
Site Detail Report

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 7

DIST/DIR: 0.26 NE

MAP ID: 5

NAME: EXXON CO USA 64810
ADDRESS: 8520 MARTIN LUTHER KING
HOUSTON TX 77033
HARRIS
CONTACT: JEFF JANOCIK

REV: 06/27/05
ID1: 113114
ID2: 0026673
STATUS:
PHONE: 214/-

SPILL/OVERFILL VARIANCE: No Variance

TANK NUMBER: 2
STATUS: Removed From Ground
STATUS DATE: 08261997
INSTALL DATE: 01011985
REGISTERED DATE: 05081986
CAPACITY: 0010000 Gallons
EXT CONTAINMENT DESIGN: Single Wall -
-

CONSTRUCTION MATERIAL: Fiberglass Reinforced Plastic (FRP)
CORROSION PROTECTION: FRP Tank or Piping (Noncorrodible) -
-

CORROSION PROT VARIANCE: No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported
STG 1 EQUIP INSTALL DATE:
STG 2 VAPOR RECOVERY EQUIP STATUS:
STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:
INSTALLER NAME:
INSTALLER LICENSE NUMBER:

TYPE OF PIPE:
PIPE MATERIAL: Fiberglass Reinforced Plastic (FRP)
PIPE DESIGN EXT CONTAINMENT: Single Wall -
PIPE CONECTORS & VALVES: - -
PIPE CORROSION PROTECTION: FRP Tank or Piping (Noncorrodible) -
- Non Corrodible Material
PIPE CORROSION PROT VARIANCE: No Variance

SUBSTANCE STORED: GASOLINE
TANK RLSE DETECTION METHODS: - - - Inventory Control
TANK RLSE DETECTION VARIANCE: No Variance
PIPE RLSE DETECTION METHODS: Auto Leak Line Detector (3.0gph for pressure piping) - - - Tightness Testing
PIPE RLSE VARIANCE: No Variance
SPILL/OVERFILL PREVENTION: Auto Flow Restrictor Valve (AFRV) - Factory Built Spill Container/Bucket/Sump - Tight -
Fill Fitting
SPILL/OVERFILL VARIANCE: No Variance

TANK NUMBER: 1
STATUS: Removed From Ground
STATUS DATE: 08261997
INSTALL DATE: 01011985
REGISTERED DATE: 05081986
CAPACITY: 0008100 Gallons
EXT CONTAINMENT DESIGN: Single Wall -
-

CONSTRUCTION MATERIAL: Fiberglass Reinforced Plastic (FRP)

- Continued on next page -

Environmental FirstSearch
Site Detail Report

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 7

DIST/DIR: 0.26 NE

MAP ID: 5

NAME: EXXON CO USA 64810
ADDRESS: 8520 MARTIN LUTHER KING
HOUSTON TX 77033
HARRIS
CONTACT: JEFF JANOCIK

REV: 06/27/05
ID1: 113114
ID2: 0026673
STATUS:
PHONE: 214/-

CORROSION PROTECTION: FRP Tank or Piping (Noncorrodible) -

CORROSION PROT VARIANCE: No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported

STG 1 EQUIP INSTALL DATE:
STG 2 VAPOR RECOVERY EQUIP STATUS:
STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:
INSTALLER NAME:
INSTALLER LICENSE NUMBER:

TYPE OF PIPE:
PIPE MATERIAL: Fiberglass Reinforced Plastic (FRP)
PIPE DESIGN EXT CONTAINMENT: Single Wall -
PIPE CONNECTORS & VALVES: - -
PIPE CORROSION PROTECTION: FRP Tank or Piping (Noncorrodible) -
- Non Corrodible Material
PIPE CORROSION PROT VARIANCE: No Variance

SUBSTANCE STORED: GASOLINE
TANK RLSE DETECTION METHODS: - - - Inventory Control
TANK RLSE DETECTION VARIANCE: No Variance
PIPE RLSE DETECTION METHODS: Auto Leak Line Detector (3.0gph for pressure piping) - - - Tightness Testing
PIPE RLSE VARIANCE: No Variance
SPILL/OVERFILL PREVENTION: Auto Flow Restrictor Valve (AFRV) - Factory Built Spill Container/Bucket/Sump - Tight -
Fill Fitting
SPILL/OVERFILL VARIANCE: No Variance

TANK NUMBER: 4
STATUS: Removed From Ground
STATUS DATE: 08261997
INSTALL DATE: 08311987
REGISTERED DATE: 05081986
CAPACITY: 0001000 Gallons
EXT CONTAINMENT DESIGN: Single Wall -

CONSTRUCTION MATERIAL: Fiberglass Reinforced Plastic (FRP)
CORROSION PROTECTION: FRP Tank or Piping (Noncorrodible) -

CORROSION PROT VARIANCE: No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported

STG 1 EQUIP INSTALL DATE:
STG 2 VAPOR RECOVERY EQUIP STATUS:
STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:
INSTALLER NAME:
INSTALLER LICENSE NUMBER:

- Continued on next page -

Environmental FirstSearch
Site Detail Report

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 6

DIST/DIR: 0.26 NE

MAP ID: 5

NAME: EXXON CO USA 6 4810
ADDRESS: 8510 MARTIN LUTHER KING
HOUSTON TX 77033
HARRIS
CONTACT:

REV: 06/27/05
ID1: 107252
ID2: 0026673
STATUS:
PHONE: 713/656-2243

SITE INFORMATION

REPORTED: 7/22/1993
ENTERED INTO SYSTEM: 10/29/1993
SITE PRIORITY: minor soil contamination - does not require a rap
SITE STATUS: Final concurrence issued, case close
PRP: EXXON COMPANY USA
PRP ADDRESS: PO BOX 2180
HOUSTON TX 77252
PRP CONTACT:
PRP PHONE: 713/656-2243

LUST INFORMATION

Environmental FirstSearch
Site Detail Report

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 9

DIST/DIR: 0.34 SE

MAP ID: 7

NAME: SOUTHPARK MARKET
ADDRESS: 9030 MARTIN LUTHER KING BLVD
HOUSTON TX 77033
HARRIS
CONTACT: HOANG NGUYEN

REV: 06/27/05
ID1: 112793
ID2: 0071662
STATUS:
PHONE: 713/661-8916

SITE INFORMATION

REPORTED: 11/6/1997
ENTERED INTO SYSTEM: 12/3/1997
SITE PRIORITY: gw impacted, no apparent threats or impacts to receptors
SITE STATUS: Final concurrence issued, case close
PRP: NGUYEN HOANG
PRP ADDRESS: PO BOX 330966
HOUSTON TX 77233
PRP CONTACT: HOANG NGUYEN
PRP PHONE: 713/661-8916

LUST INFORMATION

TANK NUMBER: 1
STATUS: Removed From Ground
STATUS DATE: 04071998
INSTALL DATE: 08311987
REGISTERED DATE: 02111999
CAPACITY: 0004000 Gallons
EXT CONTAINMENT DESIGN: -
-
CONSTRUCTION MATERIAL: -
CORROSION PROTECTION: -
-
CORROSION PROT VARIANCE: No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported
STG 1 EQUIP INSTALL DATE:
STG 2 VAPOR RECOVERY EQUIP STATUS:
STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:
INSTALLER NAME:
INSTALLER LICENSE NUMBER:

TYPE OF PIPE:
PIPE MATERIAL:
PIPE DESIGN EXT CONTAINMENT: -
PIPE CONECTORS & VALVES: - -
PIPE CORROSION PROTECTION: -
-
PIPE CORROSION PROT VARIANCE: No Variance

SUBSTANCE STORED: Unknown
TANK RLSE DETECTION METHODS: - - -
TANK RLSE DETECTION VARIANCE: No Variance
PIPE RLSE DETECTION METHODS: - - -
PIPE RLSE VARIANCE: No Variance
SPILL/OVERFILL PREVENTION: - -
SPILL/OVERFILL VARIANCE: No Variance

- Continued on next page -

Environmental FirstSearch
Site Detail Report

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 9

DIST/DIR: 0.34 SE

MAP ID: 7

NAME: SOUTHPARK MARKET
ADDRESS: 9030 MARTIN LUTHER KING BLVD
HOUSTON TX 77033
HARRIS
CONTACT: HOANG NGUYEN

REV: 06/27/05
ID1: 112793
ID2: 0071662
STATUS:
PHONE: 713/661-8916

CORROSION PROT VARIANCE: No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported
STG 1 EQUIP INSTALL DATE:
STG 2 VAPOR RECOVERY EQUIP STATUS:
STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:
INSTALLER NAME:
INSTALLER LICENSE NUMBER:

TYPE OF PIPE:
PIPE MATERIAL:
PIPE DESIGN EXT CONTAINMENT: - -
PIPE CONECTORS & VALVES: - -
PIPE CORROSION PROTECTION: -
-

PIPE CORROSION PROT VARIANCE: No Variance

SUBSTANCE STORED: Unknown
TANK RLSE DETECTION METHODS: - - -
TANK RLSE DETECTION VARIANCE: No Variance
PIPE RLSE DETECTION METHODS: - - -
PIPE RLSE VARIANCE: No Variance
SPILL/OVERFILL PREVENTION: - -
SPILL/OVERFILL VARIANCE: No Variance

TANK NUMBER: 4
STATUS: Removed From Ground
STATUS DATE: 04071998
INSTALL DATE: 08311987
REGISTERED DATE: 02111999
CAPACITY: 0003000 Gallons
EXT CONTAINMENT DESIGN: -
-

CONSTRUCTION MATERIAL:
CORROSION PROTECTION: -
-

CORROSION PROT VARIANCE: No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS: Not Reported
STG 1 EQUIP INSTALL DATE:
STG 2 VAPOR RECOVERY EQUIP STATUS:
STG 2 EQUIP INSTALL DATE:

INSTALLER COMPANY:
INSTALLER NAME:
INSTALLER LICENSE NUMBER:

TYPE OF PIPE:
PIPE MATERIAL:
PIPE DESIGN EXT CONTAINMENT: - -

- Continued on next page -

***Environmental FirstSearch
Site Detail Report***

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

LEAKING UNDERGROUND STORAGE TANKS

SEARCH ID: 9

DIST/DIR: 0.34 SE

MAP ID: 7

NAME: SOUTHPARK MARKET
ADDRESS: 9030 MARTIN LUTHER KING BLVD
HOUSTON TX 77033
HARRIS
CONTACT: HOANG NGUYEN

REV: 06/27/05
ID1: 112793
ID2: 0071662
STATUS:
PHONE: 713/661-8916

PIPE CONECTORS & VALVES:	- -
PIPE CORROSION PROTECTION:	-
	-
PIPE CORROSION PROT VARIANCE:	No Variance
SUBSTANCE STORED:	Unknown
TANK RLSE DETECTION METHODS:	- - -
TANK RLSE DETECTION VARIANCE:	No Variance
PIPE RLSE DETECTION METHODS:	- - -
PIPE RLSE VARIANCE:	No Variance
SPILL/OVERFILL PREVENTION:	- -
SPILL/OVERFILL VARIANCE:	No Variance

***Environmental FirstSearch
Site Detail Report***

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

RCRA GENERATOR SITE

SEARCH ID: 1	DIST/DIR: 0.25 NE	MAP ID: 1
---------------------	--------------------------	------------------

NAME: EXXON CO USA #64810
ADDRESS: 8520 M KING BLVD
HOUSTON TX 77033
HARRIS
CONTACT: ALDA-S POOL

REV: 2/9/04
ID1: TXD988030391
ID2:
STATUS: VGN
PHONE: 7136567709

SITE INFORMATION

UNIVERSE TYPE:

CEG - CONDITIONALLY EXEMPT SMALL QUANTITY GENERATORS: GENERATES LESS THAN 100 KG/MONTH OF HAZARDOUS WASTE

SIC INFORMATION:

ENFORCEMENT INFORMATION:

VIOLATION INFORMATION:

JOB: 31199

SEARCH ID: 4 DIST/DIR: 0.19 NE MAP ID: 4

REV: 6/24/2005
ID1: 0040171
ID2:
STATUS:
PHONE: 5126416800

NUMBER OF USTS ON SITE:	0003
NUMBER OF ASTS ON SITE:	0000
TNRCC FACILITY ID:	0040171
TNRCC CUSTOMER ID:	46459
FACILITY TYPE:	
FACILITY MANAGER:	LYN HOLMES ENV. COORD
MANAGER PHONE:	5126416800

TYPE:	Corporation
COMPANY:	DIAMOND SHAMROCK 703
ADDRESS:	1018 N SHEPHERD HOUSTON TX 77048-
PO BOX:	
CONTACT:	
CONTACT PHONE:	
AMENDMENTS:	Unknown Migration Data

TANK NUMBER:	3
STATUS:	In Use
STATUS DATE:	
INSTALL DATE:	01011972
REGISTERED DATE:	05081986
CAPACITY:	0008000 Gallons
EXT CONTAINMENT DESIGN:	-
	-
CONSTRUCTION MATERIAL:	Steel
CORROSION PROTECTION:	-
	-
CORROSION PROT VARIANCE:	No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported
STG 1 EQUIP INSTALL DATE:	
STG 2 VAPOR RECOVERY EQUIP STATUS:	Not Reported
STG 2 EQUIP INSTALL DATE:	

TYPE OF PIPE:
PIPE MATERIAL:
PIPE DESIGN EXT CONTAINMENT:
PIPE CONECTORS & VALVES:

- Continued on next page -

JOB: 31199

SEARCH ID: 4 DIST/DIR: 0.19 NE MAP ID: 4

REV: 6/24/2005
ID1: 0040171
ID2:
STATUS:
PHONE: 5126416800

SUBSTANCE STORED:	GASOLINE
TANK RLSE DETECTION METHODS:	- - - None
TANK RLSE DETECTION VARIANCE:	No Variance
PIPE RLSE DETECTION METHODS:	- - - None
PIPE RLSE VARIANCE:	No Variance
SPILL/OVERFILL PREVENTION:	- -
SPILL/OVERFILL VARIANCE:	No Variance

Site Details Page - 18

JOB: 31199

SEARCH ID: 4 DIST/DIR: 0.19 NE MAP ID: 4

REV: 6/24/2005
ID1: 0040171
ID2:
STATUS:
PHONE: 5126416800

PIPE CORROSION PROT VARIANCE:	No Variance
SUBSTANCE STORED:	GASOLINE
TANK RLSE DETECTION METHODS:	- - - None
TANK RLSE DETECTION VARIANCE:	No Variance
PIPE RLSE DETECTION METHODS:	- - - None
PIPE RLSE VARIANCE:	No Variance
SPILL/OVERFILL PREVENTION:	- -
SPILL/OVERFILL VARIANCE:	No Variance

Site Details Page - 19

JOB: 31199

SEARCH ID: 3 DIST/DIR: 0.20 NE MAP ID: 3

REV: 6/24/2005
ID1: 0057228
ID2:
STATUS:
PHONE: 713-916-1712

NUMBER OF USTS ON SITE:	0003
NUMBER OF ASTS ON SITE:	0000
TNRCC FACILITY ID:	0057228
TNRCC CUSTOMER ID:	31066
FACILITY TYPE:	Retail
FACILITY MANAGER:	ASSAD BOULOS PRES
MANAGER PHONE:	713-916-1712

TYPE:	Corporation
COMPANY:	ANA FOOD STORE
ADDRESS:	
	HOUSTON TX 77291-1098
PO BOX:	PO BOX 91098
CONTACT:	ASSAD BOULOS
CONTACT PHONE:	713-450-1199
AMENDMENTS:	Owner Contact Changed

TANK NUMBER:	3
STATUS:	Temp. Out of Use
STATUS DATE:	01011998
INSTALL DATE:	01011984
REGISTERED DATE:	01071991
CAPACITY:	0008000 Gallons
EXT CONTAINMENT DESIGN:	Single Wall - -
CONSTRUCTION MATERIAL:	Steel
CORROSION PROTECTION:	Ext Dielectric Coating/Laminate/Tape/Wrap - -
CORROSION PROT VARIANCE:	No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported
STG 1 EQUIP INSTALL DATE:	
STG 2 VAPOR RECOVERY EQUIP STATUS:	Not Reported
STG 2 EQUIP INSTALL DATE:	01011999
INSTALLER COMPANY:	
INSTALLER NAME:	
INSTALLER LICENSE NUMBER:	
TYPE OF PIPE:	
PIPE MATERIAL:	Steel
PIPE DESIGN EXT CONTAINMENT:	Single Wall - -
PIPE CONECTORS & VALVES:	- -

- Continued on next page -

JOB: 31199

JOB: 31199

MAP ID: 3

REV: 6/24/2005
ID1: 0057228
ID2:
STATUS:
PHONE: 713-916-1712

SUBSTANCE STORED:	GASOLINE
TANK RLSE DETECTION METHODS:	- - - Inventory Control
TANK RLSE DETECTION VARIANCE:	No Variance
PIPE RLSE DETECTION METHODS:	Auto Leak Line Detector (3.0gph for pressure piping) - - - Tightness Testing
PIPE RLSE VARIANCE:	No Variance
SPILL/OVERFILL PREVENTION:	Auto Delivery Shut Off Valve (ADSV) - Factory Built Spill Container/Bucket/Sump -
SPILL/OVERFILL VARIANCE:	No Variance

Site Details Page - 22

JOB: 31199

NAME:	MLK SHELL	REV:	6/24/2005
ADDRESS:	8601 MLK BLVD	ID1:	0007866
	HOUSTON TX 77033	ID2:	
	HARRIS	STATUS:	
CONTACT:	HARRIS	PHONE:	713-733-9697

NUMBER OF USTS ON SITE:	0006
NUMBER OF ASTS ON SITE:	0000
TNRCC FACILITY ID:	0007866
TNRCC CUSTOMER ID:	31066
FACILITY TYPE:	Retail
FACILITY MANAGER:	Harris
MANAGER PHONE:	713-733-9697

TYPE:	Corporation
COMPANY:	MLK SHELL
ADDRESS:	
	HOUSTON TX 77291-1098
PO BOX:	PO BOX 91098
CONTACT:	ASSAD BOULOS
CONTACT PHONE:	713-450-1199
AMENDMENTS:	Owner Contact Changed

TANK NUMBER:	1
STATUS:	Removed From Ground
STATUS DATE:	05051997
INSTALL DATE:	01011983
REGISTERED DATE:	05081986
CAPACITY:	0010000 Gallons
EXT CONTAINMENT DESIGN:	Single Wall - -
CONSTRUCTION MATERIAL:	Fiberglass Reinforced Plastic (FRP)
CORROSION PROTECTION:	Ext Dielectric Coating/Laminate/Tape/Wrap - FRP Tank or Piping (Noncorrodible) -
CORROSION PROT VARIANCE:	No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported
STG 1 EQUIP INSTALL DATE:	
STG 2 VAPOR RECOVERY EQUIP STATUS:	
STG 2 EQUIP INSTALL DATE:	
INSTALLER COMPANY:	
INSTALLER NAME:	
INSTALLER LICENSE NUMBER:	
TYPE OF PIPE:	
PIPE MATERIAL:	Fiberglass Reinforced Plastic (FRP)
PIPE DESIGN EXT CONTAINMENT:	Single Wall - -
PIPE CONECTORS & VALVES:	- -

- Continued on next page

- Continued on next page -

JOB: 31199

SEARCH ID: 5 DIST/DIR: 0.22 NE MAP ID: 6

REV: 6/24/2005
ID1: 0007866
ID2:
STATUS:
PHONE: 713-733-9697

TYPE OF PIPE:	
PIPE MATERIAL:	Fiberglass Reinforced Plastic (FRP)
PIPE DESIGN EXT CONTAINMENT:	Single Wall - -
PIPE CONECTORS & VALVES:	- -
PIPE CORROSION PROTECTION:	Ext Dielectric Coating/Laminate/Tape/Wrap - FRP Tank or Piping (Noncorrodible)
	-
PIPE CORROSION PROT VARIANCE:	No Variance
SUBSTANCE STORED:	GASOLINE
TANK RLSE DETECTION METHODS:	- - - None
TANK RLSE DETECTION VARIANCE:	No Variance
PIPE RLSE DETECTION METHODS:	- - - None
PIPE RLSE VARIANCE:	No Variance
SPILL/OVERFILL PREVENTION:	- -
SPILL/OVERFILL VARIANCE:	No Variance

Site Details Page - 24

JOB: 31199

SEARCH ID: 5 DIST/DIR: 0.22 NE MAP ID: 6

REV: 6/24/2005
ID1: 0007866
ID2:
STATUS:
PHONE: 713-733-9697

TANK NUMBER:	1
STATUS:	In Use
STATUS DATE:	
INSTALL DATE:	05151997
REGISTERED DATE:	01222001
CAPACITY:	0012000 Gallons
EXT CONTAINMENT DESIGN:	Single Wall -
	-
CONSTRUCTION MATERIAL:	Fiberglass Reinforced Plastic (FRP)
CORROSION PROTECTION:	Cathodic Protection-Factory Installed -
	-
CORROSION PROT VARIANCE:	No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS:	Two-Point System or Coaxial System

Site Details Page - 25

JOB: 31199

SEARCH ID: 5 **DIST/DIR:** 0.22 NE **MAP ID:** 6

REV: 6/24/2005
ID1: 0007866
ID2:
STATUS:
PHONE: 713-733-9697

INSTALLER COMPANY:
INSTALLER NAME:
INSTALLER LICENSE NUMBER:

SUBSTANCE STORED:	GASOLINE
TANK RLSE DETECTION METHODS:	SIR (Stat. Inventory Rconciliation) & Inventory Cntrl - - -
TANK RLSE DETECTION VARIANCE:	No Variance
PIPE RLSE DETECTION METHODS:	SIR (Stat. Inventory Rconciliation) & Inventory Cntrl - - -
PIPE RLSE VARIANCE:	No Variance
SPILL/OVERFILL PREVENTION:	Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Off Valve (ADSV) - Factory Built
Spill Container/Bucket/Sump	
SPILL/OVERFILL VARIANCE:	No Variance

TANK NUMBER:	2
STATUS:	In Use
STATUS DATE:	
INSTALL DATE:	05151997
REGISTERED DATE:	01222001
CAPACITY:	0008000 Gallons
EXT CONTAINMENT DESIGN:	Single Wall -
	-
CONSTRUCTION MATERIAL:	Fiberglass Reinforced Plastic (FRP)
CORROSION PROTECTION:	Cathodic Protection-Factory Installed -
	-
CORROSION PROT VARIANCE:	No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS:	Two-Point System or Coaxial System
STG 1 EQUIP INSTALL DATE:	01011996
STG 2 VAPOR RECOVERY EQUIP STATUS:	Balance System or Assist System
STG 2 EQUIP INSTALL DATE:	01011999

INSTALLER COMPANY:
INSTALLER NAME:
INSTALLER LICENSE NUMBER:

TYPE OF PIPE:	Pressurizes
PIPE MATERIAL:	Fiberglass Reinforced Plastic (FRP)
PIPE DESIGN EXT CONTAINMENT:	Single Wall - -
PIPE CONECTORS & VALVES:	- -

Site Details Page - 26

Environmental FirstSearch

Site Detail Report

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

REGISTERED UNDERGROUND STORAGE TANKS

SEARCH ID: 5 **DIST/DIR:** 0.22 NE **MAP ID:** 6

NAME: MLK SHELL ADDRESS: 8601 MLK BLVD HOUSTON TX 77033 HARRIS CONTACT: HARRIS	REV: 6/24/2005 ID1: 0007866 ID2: STATUS: PHONE: 713-733-9697
---	---

PIPE CORROSION PROTECTION:	-
PIPE CORROSION PROT VARIANCE:	No Variance
SUBSTANCE STORED:	GASOLINE
TANK RLSE DETECTION METHODS:	SIR (Stat. Inventory Reconciliation) & Inventory Cntrl - -
TANK RLSE DETECTION VARIANCE:	No Variance
PIPE RLSE DETECTION METHODS:	SIR (Stat. Inventory Reconciliation) & Inventory Cntrl - -
PIPE RLSE VARIANCE:	No Variance
SPILL/OVERFILL PREVENTION:	Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Off Valve (ADSV) - Tight - Fill
Fitting	
SPILL/OVERFILL VARIANCE:	No Variance
TANK NUMBER:	3
STATUS:	In Use
STATUS DATE:	
INSTALL DATE:	05151997
REGISTERED DATE:	01222001
CAPACITY:	0008000 Gallons
EXT CONTAINMENT DESIGN:	Single Wall -
	-
CONSTRUCTION MATERIAL:	Fiberglass Reinforced Plastic (FRP)
CORROSION PROTECTION:	Cathodic Protection-Factory Intalled -
	-
CORROSION PROT VARIANCE:	No Variance
STG 1 VAPOR RECOVERY EQUIP STATUS:	Not Reported
STG 1 EQUIP INSTALL DATE:	
STG 2 VAPOR RECOVERY EQUIP STATUS:	
STG 2 EQUIP INSTALL DATE:	
INSTALLER COMPANY:	
INSTALLER NAME:	
INSTALLER LICENSE NUMBER:	
TYPE OF PIPE:	Pressurizes
PIPE MATERIAL:	Fiberglass Reinforced Plastic (FRP)
PIPE DESIGN EXT CONTAINMENT:	Single Wall -
PIPE CONECTORS & VALVES:	- -
PIPE CORROSION PROTECTION:	-
	-
PIPE CORROSION PROT VARIANCE:	No Variance
SUBSTANCE STORED:	DIESEL
TANK RLSE DETECTION METHODS:	SIR (Stat. Inventory Reconciliation) & Inventory Cntrl - -
TANK RLSE DETECTION VARIANCE:	No Variance
PIPE RLSE DETECTION METHODS:	SIR (Stat. Inventory Reconciliation) & Inventory Cntrl - -
PIPE RLSE VARIANCE:	No Variance
SPILL/OVERFILL PREVENTION:	Auto Flow Restrictor Valve (AFRV) - Auto Delivery Shut Off Valve (ADSV) - Tight - Fill
Fitting	
SPILL/OVERFILL VARIANCE:	No Variance

- Continued on next page -

***Environmental FirstSearch
Site Detail Report***

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

REGISTERED UNDERGROUND STORAGE TANKS

SEARCH ID: 5

DIST/DIR: 0.22 NE

MAP ID: 6

NAME: MLK SHELL
ADDRESS: 8601 MLK BLVD
HOUSTON TX 77033
HARRIS
CONTACT: HARRIS

REV: 6/24/2005
ID1: 0007866
ID2:
STATUS:
PHONE: 713-733-9697

AST INFORMATION

Environmental FirstSearch Database Descriptions

NPL: *EPA* NATIONAL PRIORITY LIST - Database of confirmed, proposed or deleted Superfund sites.

CERCLIS: *EPA* COMPREHENSIVE ENVIRONMENTAL RESPONSE COMPENSATION AND LIABILITY INFORMATION SYSTEM - Database of current and potential Superfund sites currently or previously under investigation.

NFRAP: *EPA* COMPREHENSIVE ENVIRONMENTAL RESPONSE COMPENSATION AND LIABILITY INFORMATION SYSTEM ARCHIVED SITES - database of Archive designated CERCLA sites that, to the best of EPA's knowledge, assessment has been completed and has determined no further steps will be taken to list this site on the National Priorities List (NPL). This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

RCRA TSD: *EPA* RESOURCE CONSERVATION AND RECOVERY INFORMATION SYSTEM TREATMENT, STORAGE, and DISPOSAL FACILITIES. - Database of facilities licensed to store, treat and dispose of hazardous waste materials.

RCRA COR: *EPA* RESOURCE CONSERVATION AND RECOVERY INFORMATION SYSTEM SITES - Database of RCRA facilities with reported violations and subject to corrective actions.

RCRA GEN: *EPA* RESOURCE CONSERVATION AND RECOVERY INFORMATION SYSTEM SITES - Database of facilities that generate or transport hazardous waste or meet other RCRA requirements. LGN - Large Quantity Generators SGN - Small Quantity Generators VGN - Conditionally Exempt Generator. Included are RAATS (RCRA Administrative Action Tracking System) and CMEL (Compliance Monitoring & Enforcement List) facilities.

ERNS: *EPA/NRC* EMERGENCY RESPONSE NOTIFICATION SYSTEM - Database of emergency response actions. Data since January 2001 has been received from the National Response System database as the EPA no longer maintains this data.

STATE SITES: *TCEQ* Listing of sites contained in the State Superfund Registry, listing of all sites in the Voluntary Cleanup Program (VCP) and the Innocent Owner/Operator Program (IOP). Some VCP and IOP sites are noted as having institutional controls placed on them.

SWL: *TCEQ* Listing of all permitted solid waste landfills, transfer stations, and incinerators

OTHER: TCEQ Texas Industrial Hazardous Waste Notice of Registration (IHW NOR) data. The TCEQ enters all information submitted by industrial and hazardous waste transporters, receivers (including recyclers), generators and one time shipments into a database that tracks industrial and hazardous waste generation and management activities in the state of Texas. All facilities of these types receive a solid waste registration number.

REG UST/AST: TCEQ Listing of all underground petroleum storage tanks

LEAKING UST: TCEQ Listing of all leaking underground petroleum storage tanks

OTHER: EPA SECTION SEVEN TRACKING SYSTEM (SSTS) – database of registration and production data for facilities which manufacture pesticides. AEROMETRIC INFORMATION RETRIEVAL SYSTEM (AIRS) – database of detailed information pertaining to sites which submit air emissions reports. Developed under the Clean Air Act, this database also maintains data on compliance status and enforcement actions.

RADON: NTIS NATIONAL RADON DATABASE - EPA radon data from 1990-1991 national radon project collected for a variety of zip codes across the United States.

Environmental FirstSearch Database Sources

NPL: *EPA* Environmental Protection Agency

Updated quarterly

CERCLIS: *EPA* Environmental Protection Agency

Updated quarterly

NFRAP: *EPA* Environmental Protection Agency.

Updated quarterly

RCRA TSD: *EPA* Environmental Protection Agency.

Updated quarterly

RCRA COR: *EPA* Environmental Protection Agency.

Updated quarterly

RCRA GEN: *EPA* Environmental Protection Agency.

Updated quarterly

ERNS: *EPA/NRC* Environmental Protection Agency

Updated semi-annually

STATE SITES: *TCEQ* The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration, Remediation Division

Updated quarterly

SWL: *TCEQ* The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration, Waste Permits Division, Municipal Solid Waste Permits Section

Updated annually

OTHER: *TCEQ* The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration

Updated quarterly

REG UST/AST: *TCEQ* The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration, Waste Permits Division, Petroleum Storage Tank Program

Updated quarterly

LEAKING UST: *TCEQ* The Texas Commission on Environmental Quality's Office of Permitting, Remediation and Registration, Waste Permits Division, Petroleum Storage Tank Program

Updated quarterly

OTHER: *EPA* Environmental Protection Agency

Updated quarterly

RADON: *NTIS* Environmental Protection Agency, National Technical Information Services

Updated periodically

Environmental FirstSearch
Street Name Report for Streets within 1 Mile(s) of Target Property

TARGET SITE: 9301 MERLE ST
 HOUSTON TX 77033

JOB: 31199

Street Name	Dist/Dir	Street Name	Dist/Dir
Airport Blvd	0.86 SW	Mallow St	0.36 NW
Alvin St	0.76 NW	Marcy Dr	0.59 NW
Angleton St	0.80 NW	Martin Luther King J	0.18 NE
Anna Held St	0.84 SE	Meadow Park Dr	0.99 SW
Arden Ct	0.89 SW	Medford Dr	0.18 NE
Ashburn Ave	0.23 SE	Merle St	0.02 SW
Bayfield Dr	0.32 SE	Murr Way	0.94 SW
Belarbor St	0.59 N-	Myrtlewood Dr	0.69 NW
Belbay St	1.00 NE	Noel St	0.28 SW
Belcrest St	0.52 N-	Northridge Dr	0.81 NE
Beldart Ct	0.40 NW	Osprey Dr	0.97 SE
Beldart St	0.32 NW	Overdale St	0.07 SE
Belgard St	0.93 NE	Panay Dr	0.68 NW
Bellfort Ave	0.63 NW	Paradise Ln	0.96 SW
Bellfort Ct	0.68 NW	Paula St	0.49 SW
Belmark St	0.47 NW	Peacock	0.67 SW
Belneath St	0.37 NW	Pederson Dr	0.24 SW
Brinkley Ave	0.71 NW	Pensdale Dr	0.76 NW
Carmen St	0.02 SW	Phlox St	0.98 NW
Chain St	0.73 NW	Redfern Dr	0.64 NW
Clearway Dr	0.52 SE	Reed Rd	0.12 NW
Clover St	0.41 NW	Richfield Ln	0.97 SW
Coffee St	0.80 NW	Ricky St	0.51 SE
Colt	0.64 SW	Ridgeway Dr	0.86 NE
Crestmont St	0.61 NE	Rockford Dr	0.22 NW
Cullen Blvd	0.95 NW	Rue St	0.42 S-
Delilah St	0.97 NW	Saint Lo Rd	0.30 NW
Dobie	0.86 SW	Sandhurst Dr	0.49 NW
Elmlawn Dr	0.47 SE	Schevers St	0.09 SE
Faircroft Dr	0.51 SE	Sharondale Dr	0.06 NW
Flamingo Dr	0.27 N-	Silver Stone St	0.91 SE
Glen Hollow Dr	0.54 NW	Simsdale St	0.13 SE
Glenhurst Dr	0.97 NE	Southbank	0.41 -E
Glenside St	0.11 NW	Southbrook Dr	0.18 SE
Groveton St	0.57 SE	St Lo Rd	0.15 NW
Heron Dr	0.16 NE	Sunbeam St	0.37 SE
Herschelwood St	0.55 NW	Teneha Dr	0.44 SW
Higgins St	0.17 SW	Thrush Dr	0.21 N-
Hilda St	0.57 NW	Vasser Rd	0.23 SE
Hirondel St	0.05 N-	Vine Arbor St	0.07 SE
Jethro St	0.56 SW	Waterford Dr	0.73 SE
Jezebel St	0.57 SW	Wenda St	0.28 SW
Jutland Rd	0.57 NW	Westover St	0.42 NW
Kenilwood Dr	0.97 NE	Willow Glen Dr	0.91 NE
Kildee Park	0.56 NE	Wilmington St	0.10 S-
Lakefield Dr	0.63 SE	Windemere St	0.65 NE
Larkspur St	0.46 NW	Woodgreen St	0.27 SE
Lyndhurst Dr	0.74 NE		

Environmental FirstSearch
Street Name Report for Streets within 1 Mile(s) of Target Property

TARGET SITE: 9301 MERLE ST
HOUSTON TX 77033

JOB: 31199

<u>Street Name</u>	<u>Dist/Dir</u>	<u>Street Name</u>	<u>Dist/Dir</u>
Maggie St	0.79 NW		


APPENDIX-D



SITE: 9301 MERLE ST.
SOURCE: ASCS
DATE: 04-03-44
COUNTY: HARRIS
SCALE: 1" = 700'




SITE: 9301 MERLE ST.
SOURCE: ASCS
DATE: 04-26-53
COUNTY: HARRIS
SCALE: 1" = 700'



SITE: 9301 MERLE ST.
SOURCE: WALLACE
DATE: 02-21-69
COUNTY: HARRIS
SCALE: 1" = 700'



SITE: 9301 MERLE ST.
SOURCE: TXDOT
DATE: 03-26-79
COUNTY: HARRIS
SCALE: 1" = 700'



SITE: 9301 MERLE ST.
SOURCE: TXDOT
DATE: 12-01-86
COUNTY: HARRIS
SCALE: 1" = 700'



SITE: 9301 MERLE ST.
SOURCE: USGS
DATE: 1996
COUNTY: HARRIS
SCALE: 1" = 700'



SITE: 9301 MERLE ST.
SOURCE: USDA
DATE: 2004
COUNTY: HARRIS
SCALE: 1" = 700'


APPENDIX-E



Subject site



Northwest view of property (partial)



Sites to the west



Sites to the south



Sites to the east



Sites to the north